

1/22




FIG. 1a




FIG. 1e




FIG. 1b




FIG. 1f





FIG. 1c




FIG. 1g




FIG. 1d




FIG. 1h

2/22




FIG. 2a




FIG. 2b

09/833,084, FIG. 2a

3/22




FIG. 2c




FIG. 3

Patent No. 09/833,084

4/22




FIG. 4a




FIG. 4b

5/22




FIG. 5a




FIG. 5b

6/22




FIG. 6




FIG. 7a




FIG. 7b

7/22




FIG. 8




FIG. 9a

8/22




FIG. 9b






FIG. 10a

FIG. 10a



9/22



10/22




FIG. 11b




FIG. 12a

11/22




FIG. 12b





FIG. 13

12/22



Incident Polarization Angle

FIG. 14

FIG. 14

13/22

FIG. 15





FIG. 15

14/22




Overlay Misregistration (nm)

FIG. 16

FIG. 16 of 4346636

15/22



Overlay Misregistration (nm)

FIG. 17

16/22




FIG. 18

FIG. 18



17/22




FIG. 19

FIG. 19

18/22




FIG. 20

Pat. No. 4,966,650

19/22




FIG. 21

20/22




FIG. 22

FIG. 22

21/22




FIG. 23

FIG. 23 10000000

22/22




FIG. 24

FIG. 24 4306650